Page 1

56167419 A



(11) Publication number:

56167419 A

## Generated Document.

## PATENT ABSTRACTS OF JAPAN

(51) Ind. Cl.: B29D 17/00

(21) Application number: **5507**2969

30.05.80 (22) Application date:

23.12.81 (43) Date of application (30) Priority: publication:

(84) Designated contracting states:

(71) Applicant: TOPPAN PRINTING CO LTD (72) Inventor: FUJITA TOSHIJI SAITO AKIHIDE

(74) Representative:

DENSITY INFORMATION RECORDING CARRIER (54) MANUFACTURING DEVICE FOR HIGH-

(57) Abstract:

device, in which a resin injecting hole which can acquire a recording carrier material and an air vent with a valve coated with an ultraviolet shieling with no strain, etc. in a short time, ransmitting ultraviolet rays and PURPOSE: To obtain the titled device are mounted at the fixed ocations of the second mold

Page 2 of 3

httms://www.delphion.com/cgi-hin/viewnat.cmd/JP56167419A2

56167419 A


economizing the material cost, etc.

cope 11 and the ultravioler irradiating shutters 23 are opened and ultraviolet air vent 13, the disc molding space is lise is extracted from the stamper 31 contacted by proper pressure. A disc fevice 21 are elevated and a molded molding space taking discoid shapes by actuating a valve device 14 of an stamper 31 is sucked under vacuum irradiating device 21 are let fall and CONSTITUTION: A stamper 31 is brought to a vacuum condition and rays are irradiated. The shutters 23 mounted to a drag I by means of a are colsed after resin hardens, the fixed, a cope 11 and an ultraviolet through a resin injecting hole 12, under vacuum and fast stuck and mounting member 8, and sucked the vent 13 is closed, ultraviolet hardening type resin is injected the cope 11 and the drag 1 are of the concave sections of the

COPYRIGHT: (C)1981, JPO& Japio

Page 3 of 3

https://www.delphion.com/cei-bin/viewnat.cmd/IP56167419A2



## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.